

SEE PIPING SCHEMATIC AND INSTALLATION REQUIREMENTS TO ASSURE PROPER OPERATION.


USE A HEAT GUN AND DISH SOAP TO INSTALL PVC HOSE ONTO COMBINATION NIPPLES.


HOOK-UP KITS MAY BE SHIPPED LOOSE AS UNASSEMBLED COMPONENTS.

CONTROL CABINET IS NOT SHOWN ON THIS DRAWING.

----- SCIENCO/FAST SUPPLIED COMPONENTS

SEE PAGE 2 OF 5 FOR BILL OF MATERIALS AND PART NUMBERS.



| REV | DESCRIPTION | BY | DATE |
|---|-------------|--------------------------|-----------|
|  SCIENCO/FAST® 200 SUN VALLEY CIRCLE FENTON, MO. 63026-4691 U.S.A. PHONE: 314-756-9300 FAX: 314-756-9306 | | | |
| THIS DRAWING AND INFORMATION CONTAINED THEREIN IS THE PROPERTY OF SCIENCO/FAST SYSTEMS AND IS LOANED WITH THE EXPRESSED AGREEMENT THAT IT WILL NOT BE REPRODUCED, COPIED, OR OTHERWISE DISTRIBUTED, DIRECTLY OR INDIRECTLY, AND WILL NOT BE USED IN WHOLE OR IN PART, TO FURNISH ANY INFORMATION FOR THE MANUFACTURING OF EQUIPMENT OR APPARATUS WITHOUT WRITTEN PERMISSION OF SCIENCO/FAST SYSTEMS FIRST OBTAINED AND SPECIFIC TO EACH CASE. | | | |
| SYSTEM | | SCIENCO/FAST MARINE/FAST | |
| CUSTOMER | | CUSTOMER NAME HERE | |
| TITLE L5X SYSTEM DRAWING COMPONENT ARRANGEMENT | | | |
| SCALE | 1"=1'-0" | DRAWN | SC |
| SIZE | N/A | CHECKED | SC |
| | | APPROVED | N/A |
| | | DATE | 1/2024 |
| CONTRACT NO. | MODEL NO. | DRAWING NO. | SHEET NO. |
| | | MASTER CU101 | 1 of 5 |